


8613 – Internal Photo Record

New Apartments and
Demolition of the Laban
Tansey Building at the
Former Factory Works site
Between Upper Bond St.
/ Druid St. Hinckley



1.0 Ground Floor

Existing Images / Key Plan



Ground Floor Plan Extract – see dwg 012




Main building, ground floor.
Front windows and north wall. Looking north-east.



Main building, ground floor.
Blocked windows on rear wall and inserted doorway. Looking south-west.

1.0 Ground Floor

Existing Images / Key Plan



Ground Floor Plan Extract – see dwg 012




Inside of goods entrance.
Looking east.




Gable-ended building, ground floor. Original back wall and windows.
Looking east.

1.0 Ground Floor

Existing Images / Key Plan




Ground Floor Plan Extract – see dwg 012



Rear workshop. Viewed from goods entrance.
Looking north-east.

2.0 First Floor

Existing Images / Key Plan



First Floor Plan Extract – see dwg 013




Main building, first floor.
Blocked windows on rear wall and inserted doorway. Looking south-west.




Main building, first floor.
Front windows. Looking north-east.

2.0 First Floor

Existing Images / Key Plan



First Floor Plan Extract – see dwg 013



Gable-ended building, first floor. Front windows.
Looking east.



Gable-ended building, first floor. Blocked remnant of rear Venetian
windows in gable.
Looking north-east.