



Rear view of cottage. All windows to be replaced due to rotting. French door proposal to replace middle window into utility room for access and natural light/ ventilation.

3 x Velux windows, one for each upstairs room, not changing structure or elevation of existing roof.



Interior view of current bathroom window to be replaced with French doors. Showing ability to avoid removing any historic fabric.



Front view of cottage showing 6 x windows and 1 x door in need of replacement due to rot.

Chimney stack unstable, requesting permission to rebuild with existing bricks to make safe and prolong life.