

## 8613 – Internal Photo Record


---

New Apartments and  
Demolition of the Laban  
Tansey Building at the  
Former Factory Works site  
Between Upper Bond St.  
/ Druid St. Hinckley



# 1.0 Ground Floor

## Existing Images / Key Plan



Ground Floor Plan Extract – see dwg 012




Main building, ground floor.  
Front windows and north wall. Looking north-east.



Main building, ground floor.  
Blocked windows on rear wall and inserted doorway. Looking south-west.

# 1.0 Ground Floor

## Existing Images / Key Plan



Ground Floor Plan Extract – see dwg 012




Inside of goods entrance.  
Looking east.




Gable-ended building, ground floor. Original back wall and windows.  
Looking east.

# 1.0 Ground Floor

## Existing Images / Key Plan




Ground Floor Plan Extract – see dwg 012



Rear workshop. Viewed from goods entrance.  
Looking north-east.

## 2.0 First Floor

### Existing Images / Key Plan



First Floor Plan Extract – see dwg 013




Main building, first floor.  
Blocked windows on rear wall and inserted doorway. Looking south-west.




Main building, first floor.  
Front windows. Looking north-east.

## 2.0 First Floor

### Existing Images / Key Plan



First Floor Plan Extract – see dwg 013



Gable-ended building, first floor. Front windows.  
Looking east.



Gable-ended building, first floor. Blocked remnant of rear Venetian windows in gable.  
Looking north-east.