



	service cover		center screen
	bank line		triangular manhole
	fence		sheepbark
	rolling on bank		gate
	drain, channel		fence
	gate		fence
	well		edge of surface
	vegetation line		Ground Name and Level
			0 100.00 Ground level

	step cook		island
	manhole		gate post
	VP		electric
	rolling pipe		5 level Service line
	VP		FLW - Threshold Level
	television		DWC - dump course level
	water valve		TCR - Top Coat line
	GAS		TV
	fire hydrant		Levels are generally shown on the side of the aerial
	water valve		to which it refers
	inspection		Levels shown along the left hand side are taken in the center
	letter box		
	road sign		
	lamp post		
	electric pole		
	telegraph post		



This plan has been surveyed to the scale shown
Caution should be exercised when enlargements are made

Some services may not have been surveyed due to parked vehicles or other obstructions

All dimensions have been measured or estimated from ground level, unless stated otherwise.

Tree species shown should be treated with caution and expert identification is advised.

Drainage Information has been taken from a surface inspection and should be treated as approximate only.

All critical dimensions should be confirmed onsite prior to the commencement of any works.

PROJECT

**Manor View
Aston Flamville Road
Hinckley LE10 3AA**

C L B Surveys Ltd
38 Forest View
Overseal
Swadlincote
Derbyshire
DE12 6GZ

Telephone: 07843377917
Email: admin@clbsurveys.co.uk

copyright reserved