

23/010247DISCON

Condition 5 Supporting photos showing barrier membrane being installed















