

Parking arrangement to be reconfigured as shown on drawing PD-02