J BURKE BEng(Hons) CEng MIStructE MICE MaPS
42 Woodland Road
Hinckley
Leicestershire
LE10 1JG
Tel/Fax 01455 636404
jburke.consulting@btinternet.com



HINCKLEY & BOSWORTH BOROUGH COUNCIL

HINCKLEY & DISTRICT MUSEUM, LOWER BOND STREET, HINCKLEY.

Structural Engineers Report

Job No 08425

References: Survey notes 28-04-08

Report Prepared by:
Jonathan Burke BEng (Hons) CEng MIStructE MICE MaPS

DEVELOPMENT SERVICES
0 3 FEB 2009
RECEIVED



Fungal growth



15mm
interface crack

DEVELOPMENT
SERVICES
0 3 FEB 2009
RECEIVED

J BURKE BEng(Hons) CEng MStructE MICE MaPS



30mm gap between chimney and gable wall

DEVELOPMENT SERVICES
03 FEB 2009
RECEIVED

J BURKE BEng(Hons) CEng MStructE MICE MaPS



2003 repointing evident but continued bulging.



Bulging in line with former attic and first floors.

DEVELOPMENT SERVICES
0 3 FEB 2009
RECEIVED

J BURKE BEng(Hons) CEng MStructE MICE MaPS



Lime mortar beginning to come out on panel periphery.



Bulging end gable.

DEVELOPMENT SERVICES
03 FEB 2009
RECEIVED