curious ECOLOGISTS

Curious Ecologists
Ecological Consultants
156, Meadow Lane
Coalville
LE67 4DP
Tel. 01530 457440
curiousecologists@yahoo.co.uk

Landmark Planning Ltd
10 Salisbury Road
Leicester
LE1 7QR
FAO Phil Rowland
6th June 2010

Ref: Bat Survey at The Barn at Home Farm, Hall Lane, Osbaston, Nr Nuneaton, Warks., CV13 0BW

Name of Client: Mr D. Bloor
Name of Agent: Landmark Planning Ltd, contact- Phil Rowland
Address Of Agent: 10 Salisbury Road, Leicester, LE3 7QR
Date of Survey: 10th May 2010
Planning Application Number: 09/00934/FUL
Grid Reference of survey site: SK 4254 0437
Name of Surveyor: A.B.Gibney BSc (Hons), MIEEM
Licence Numbers: Bat 20093453 issued by Natural England

The following letter is a brief report on a follow up survey suggested in the recommendations of the ecology report produced by myself, as amended 12th February 2010. The recommendation stated 'Works on buildings 1 & 4 should not be started until the bat loft is completed in building 5, and these works on buildings 1 & 4 would be best undertaken between October and April, when bats are unlikely to be present. Works on buildings 1 & 4 can only be carried out at other times if a licensed bat worker has carried out surveys to ascertain that bats aren't present in the roosts.' This is part of the continuing watching brief and monitoring of this development.

In brief, a dusk visit was undertaken at the site on 10th May 2010, to check that the bat loft in building 5 had been completed and to check whether there was any evidence of bats in building 1 & 4 prior to the commencement of works on these two buildings.

The findings were as follows:

- The bat loft in building 5 was completed and it was agreed that a further visit be undertaken to check for bat droppings or other evidence of use by bats, could be found in this loft at a later date.

- Buildings 1 & 4 were thoroughly searched for any fresh evidence of bats, and were searched for the bats themselves, using a bat detector and red filtered torch. No fresh droppings were found and there were no bats found to be present in either building.

- Building 1 had been re-roofed, as the roof had collapsed over the winter period, due to the weight of snow on it. No further roofing works were to be undertaken in this building until September at the earliest, when it was proposed to fit insulation between the rafters. It was agreed that a further visit be undertaken nearer this time to check for any evidence of bats.

- The building works in Building 4 were to commence as soon as possible, as it was ascertained that there were no bats present in this building. It was also ascertained that there no birds nesting in this building, so again it would be better to commence works before any nests were started. By starting the works, the disturbance caused by the works should prevent any birds or bats trying to take up residence at a later date.

Letter and survey undertaken and produced by
Alan Bernard Gibney BSc (Hons), MIEEM - Ecologist (Curious Ecologists)