

Tree Protection Plan

Trees outside Zone of influence

Note method statement for root intrusion
In BS5837 Tree Report. No build in the RPZ.
Services and replacement of tarmac only.

No build within the area of RPZ

— Tree Protection fencing

