11/00409/FUL DISCONS. YES

Colin J. Rusted, M.C.I.A.T.

Architectural Technician & Surveyor
Technical Design Service

Bungalow Farm
Stoke Road, Hinckley
Leicestershire, LE10 3EA

Telephone: (01455 634000)

The Development Dept.,
Hinckley & Bosworth Borough Council,
Council Offices,
Hinckley.

11/11/2011

Dear Sir,

re Residental Development land rear of 30-42 Hinckley Road,
Stoke Golding.
Ref. 11/00409/FUL.

Further to discussions between yourselves and Mr. Wakefield regarding the above development, with particular reference to the discharge of 'Conditions' , I confirm the following :-

1. I understand that an alternative roof tile has been suggested i.e. Marley 'Ashmore' Smooth Brown 333 x 267 in size in lieu of the Marley Flat tile originally submitted.

A sample is being submitted for your approval,

2. The existing junction of the service road with Hinckley Road, I confirm, is surfaced in Block Paving as originally agreed when the earlier development was completed some years ago.

3. The service road is surfaced in 25mm thick crushed stone.

I trust this information satisfies your outstanding queries.

Yours faithfully,

C.J. Rusted

.....

C.J. Rusted MCIAT