

KIRKBY HOUSE FARM
Church Road
Kirkby Mallory
Leicestershire LE9 7QE
NOTE
Some doors are larger than standard
due to original fittings.
June 2008
Garage
7.0 x 6.8
Car Park
Sun Room
2.4 x 5.0
Utility
4.8 x 3.1
Back
Entrance
Side
Entrance
Kitchen
4.7 x 5.0
Pantry
Rear
Entrance
Stairs &
Hall
3.6 x 3.0
Up
Fire
Extinguisher
Hall
Cellar
Study
4.9 x 2.5
Up
Stairs
Side
Entrance
Lounge
3.9 x 4.9
Lounge
4.3 x 5.0
Boot Room
2.3 x 2.4
Dining Room
7.4 x 4.5
Front
Entrance
Double vehicle
entry access
Garage