



GEO SHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 8
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 9
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 10
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 11
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 50
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEOSHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 51
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEOSHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 52
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 53
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEOSHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 54
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEOSHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 55
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 46
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEOSHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 47
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 48
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 49
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEOSHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited


R4 Civils – Plot 5
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited


R4 Civils – Plot 6
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEOSHIELD

Verification Certificate

Date: 08 June 2026

Omega Lining Solutions Limited

R4 Civils – Plot 7
Barlestone, Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries were installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services

