




ALL DRAWINGS PREPARED BY ANDREW
LARGE SURVEYORS LTD ARE TO BE
UTILISED FOR PLANNING PURPOSES
ONLY

EXISTING SITE:

VISIBILITY IS IMPAIRED BY
HEDGEROWS WHICH ARE UNDER THE
OWNERSHIP OF THE APPLICANT IN A
NORTH EASTERN DIRECTION.

PROPOSED VISIBILITY PLAN SHOWS
THE HEDGEROW RECONFIGURED TO
OBTAIN THE REQUIRED VISIBILITY.

AndrewLarge
surveyors LTD

HILMARCO
THORNTON LANE
MARKFIELD
LEICESTERSHIRE
LE67 9RP
EXISTING VISIBILITY
SCALE: 1:500@A1