



GEO SHIELD

Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 1


**Barlestone
Barton Road
Osbaston
Nuneaton
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 2


**Barlestone
Barton Road
Osbaston
Nuneaton
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 3


**Barlestone
Barton Road
Osbaston
Nuneaton
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 4


**Barlestone
Barton Road
Osbaston
Nuneaton
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 35


**Barlestone
Barton Road
Osbaston
Nuneaton
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 36


Barlestone
Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 41


**Barlestone
Barton Road
Osbaston
Nuneaton
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 42

**Barlestone
Barton Road
Osbaston
Nuneaton
CV13 0EU**


The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

A handwritten signature in black ink, appearing to read 'Paul Colbeck'.

Paul Colbeck
Director of Site Services





GEO SHIELD

Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 35


Barlestone
Barton Road
Osbaston
Nuneaton
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services





Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 36

**Barlestone
Barton Road
Osbaston
Nuneaton
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

Paul Colbeck
Director of Site Services

