



# GEO SHIELD

## Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 37


**Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





## Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 38


Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





# GEO SHIELD

## Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 26


**Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





## Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 27

**Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU**


The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

A handwritten signature in black ink, appearing to read 'Paul Colbeck', is positioned above the printed name.

**Paul Colbeck**  
Director of Site Services





# GEO SHIELD

## Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 28


**Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





## Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 29

**Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU**


The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

A handwritten signature in black ink, appearing to read 'Paul Colbeck'.

**Paul Colbeck**  
Director of Site Services





# GEO SHIELD

## Verification Certificate

Date: 28 July 2025

**Omega Lining Solutions Limited**

**R4 Civils - Plot 30**


**Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





# GEO SHIELD

## Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 31


**Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





# GEOSHIELD

## Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 32


**Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





# GEO SHIELD

## Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 33


**Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





# GEO SHIELD

## Verification Certificate

Date: 28 July 2025

Omega Lining Solutions Limited

R4 Civils - Plot 34

**Barlestone  
Barton Road  
Osbaston  
Nuneaton  
CV13 0EU**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services

