

CUSTOMER JOB NO. 105396 - 4369 - Harry Martin

Project Name R4 Civils, Barlestone

Customer Details

Name Omega Lining Solutions Ltd
Address Heanor Road
Loscoe
Heanor Derbyshire DE75 7JT

Site Details

Name R4 Civils, Barlestone
Address Barton Road
Osbaston
Nuneaton CV13 0EU

Work Completed

SITE VISIT DATE:05/09/25.

VISIT / REPORT NUMBER: R5

INSPECTION & VALIDATION DETAILS:

Verification was carried out on the complete line out of JUTA GP1 Gas Barrier on 17 plots, installed by Omega Lining Solutions Ltd.

All laps of the adjacent sheets of membrane have been successfully welded using a hot air leister and silicone roller tool.

The installers have sealed all corners, door thresholds and pipe penetrations using JUTA GP1 SAM.

Air lance supported by Pick + Probe testing has identified ONE fault across the specified plots.

Verified in accordance with CIRIA 735.

AREA / GRID LINE / PLOT NUMBER SIGNED:
PLOTS - 12-25,43,44,45.

OUTSTANDING REMEDIATIONS:N/a.

EXPECTED NEXT VISIT DATE:TBC.

Please note this is not a Verification Report

WHEN REPORT INVOICE HAS BEEN PAID IN FULL THE REPORT WILL BE ISSUED.
ON SETTLEMENT OF FINAL ACCOUNT THE VERIFICATION CERTIFICATE WILL BE ISSUED.

Customer:

Rhys Wilkins

Print Name



Signature