

Appendix 4: Photographic Archive: Photo Register, Photographic Survey and Survey Location Plans

All photographs were taken by Joseph Pole in January 2024. The photographs are numbered to be cross referenced with the below descriptions, and their locations are plotted on the photo location plans. All images taken as part of this survey are included here.

Photograph Register

Frame	Subject and Photo Location
1	The north elevation. Taken from the northeast.
2	The south elevation. Taken from the south.
3	The south elevation. Taken from the southwest.
4	The east elevation. Taken from the east.
5	Detail of bay window to the south elevation. Taken from the southeast
6	Detail of door and window to the south elevation. Taken from the south.
7	Detail of plaster panel above the doorway, blocking original fanlight. Taken from the south.
8	The south elevation. Taken from the southwest.
9	Window to the central projecting bay of the south elevation. Taken from the south.
10	First floor window to the central projecting bay of the south elevation. Taken from the south.
11	Western bays of the south elevation. Taken from the south.
12	Detail of ground floor window to the eastern bay of the south elevation. Taken from the south.
13	East elevation of the swimming pool extension. Taken from the east.
14	Windows to the northern bay of the east elevation. Taken from the northeast.
15	The north elevation. Taken from the north.
16	Western bays of the north elevation. Taken from the north.
17	Detail of western bay to the north elevation. Taken from the north.
18	Detail of western bay to the north elevation. Taken from the north.
19	Projecting bay to the north elevation containing the main entrance. Taken from the north.
20	Main entrance to the north elevation. Taken from the north.
21	North and east walls of room 1. Taken from the southwest.
22	Chandelier and ceiling rose to room 1. Taken from the southwest.

23	Doorways and door to the safe in the west wall of room 1. Taken from the east.
24	Fireplace to room 1. Taken from the northwest.
25	East wall of room 2. Taken from the northwest.
26	Bay window to the south wal of room 2. Taken from the northwest.
27	West wall of room 2. Taken from the east.
28	Chandelier and ceiling rose to room 2. Taken from the northwest.
29	Fireplace to room 2. Taken from the west.
30	Room 3. Taken from the south.
31	Room 3. Taken from the north,
32	Detail of plaster work to the ceiling, chandelier and ceiling rose, room 3. Taken from the south.
33	Stairs to room 3. Taken from the northwest.
34	Stairs to room 3. Taken from the east.
35	Detail of stair and landing to room 3. Taken from the north.
36	Detail of stair and landing to room 3. Taken from the north.
37	Detail of stair and landing to room 3. Taken from the north.
38	Detail of stair and landing to room 3. Taken from the north.
39	Detail of the banister to the landing. Taken from the south.
40	North and east walls of room 4. Taken from the southwest.
41	South and west walls of room 4. Taken from the northeast.
42	Fireplace to room 4. Taken from the
43	Detail of doorway to the east wall of room 4. Taken from the west.
44	Window to the south wall of room 4. Taken from the west.
45	East wall of room 4. Taken from the
46	South and west walls of room 5. Taken from the northeast.
47	East wall of room 5. Taken from the west.
48	North wall of room 5. Taken from the south.
49	Window to the north wall of room 5. Taken from the south.
50	Room 6. Taken from the east.

51	Room 6. Taken from the west.
52	East wall of room 7. Taken from the southwest.
53	North wall of room 7. Taken from the south.
54	West wall of room 7. Taken from the east.
55	Detail of timber beam and ceiling rose, room 7. Taken from the west.
56	South wall of room 8. Taken from the north.
57	Detail of plaster to ceiling and ceiling rose, room 8. Taken from the north.
58	North wall of room 8. Taken from the south.
59	North wall of room 9. Taken from the south.
60	West wall of room 9. Taken from the east.
61	North wall of room 10. Taken from the south.
62	North wall of room 10. Taken from the south.
63	West wall of room 11. Taken from the east.
64	Southern side of room 11. Taken from the northeast.
65	Swimming pool in room 11. Taken from the south.
66	View into the toilet to the north of the swimming pool. Taken from the south.
67	View across the changing rooms to the north of the swimming pool in room 11. Taken from the
68	Image of the cellar
69	Image of the cellar
70	Room 12 facing south. Taken from the north,
71	Room 12 facing north. Taken from the south,
72	East and north walls of room 13. Taken from the southwest.
73	South wall of room 13. Taken from the north.
74	North and east walls of the ensuite to room 13. Taken from the south.
75	Ensuite, facing south. Taken from the north.
76	Dressing room to room 13. Taken from the south.
77	Dressing room to room 13. Taken from the north.
78	North wall of room 14. Taken from the south.
79	South wall of room 14. Taken from the north.

80	South and west walls of room 15. Taken from the north
81	West wall of room 15, showing location the fireplace, taken from the northeast.
82	North and east walls of room 15. Taken from the southwest.
83	South and east walls of room 16. Taken from the northwest.
84	North and west walls of room 16. Taken from the southeast.
85	Room 17 facing north. Taken from the south.
86	Room 17 facing south, taken from the north.
87	South and east walls of room 18. Taken from the northwest.
88	North and west walls of room 18. Taken from the southeast.
89	North and west walls of room 19. Taken from the southeast.
90	South and east walls of room 19. Taken from the northwest.
91	South and east walls of room 20. Taken from the northwest.
92	North wall of room 20. Taken from the south.
93	North and west walls of room 21. Taken from the southeast.
94	South and west walls of room 21. Taken from the northwest.



Ph 1



Ph 2



Ph 3



Ph 4



Ph 5



Ph 6



Ph 7



Ph 8



Ph 9



Ph 10



Ph 11



Ph 12



Ph 13



Ph 14



Ph 15



Ph 16



Ph 17



Ph 18



Ph 19



Ph 20



Ph 21



Ph 22



Ph 23



Ph 24



Ph 25



Ph 26



Ph 27




Ph 28



Ph 29



Ph 30



Ph 31



Ph 32



Ph 33



Ph 34



Ph 35



Ph 36



Ph 37



Ph 38



Ph 39



Ph 40



Ph 41



Ph 42



Ph 43



Ph 44



Ph 45



Ph 46



Ph 47



Ph 48



Ph 49



Ph 50




Ph 51



Ph 52



Ph 53



Ph 54



Ph 55



Ph 56



Ph 57



Ph 58



Ph 59



Ph 60



Ph 61



Ph 62



Ph 63



Ph 64



Ph 65



Ph 66



Ph 67



Ph 68



Ph 69



Ph 70



Ph 71



Ph 72



Ph 73



Ph 74



Ph 75



Ph 76



Ph 77



Ph 78



Ph 79



Ph 80



Ph 81



Ph 82



Ph 83



Ph 84



Ph 85



Ph 86



Ph 87



Ph 88



Ph 89



Ph 90



Ph 91



Ph 92




Ph 93



Ph 94

Photograph Location Plan of Ground Floor



Photograph Location Plan of the First Floor

