

10 PLATES



Plate 1: General aerial view of Wood Farm from the west



Plate 2: General aerial view from the southeast



Plate 3: General aerial view from the east



Plate 4: General aerial view from the north




Plate 5: Front boundary wall along Stanton Lane with datestone 'Wood Farm 1755'




Plate 6: Boundary wall with foundation plaque



Plate 7: Building 1 – aerial view of the southeast elevation with cross-wing Building 2



Plate 8: Building 1 – aerial view of the northeast gable and adjacent Building 2



Plate 9: Building 1 – southeast elevation



Plate 10: Building 1 – southeast elevation, detail of construction joint and blocked ventilation slit (arrow)



Plate 11: Building 1 – northeast elevation




Plate 12: Building 1 – northeast elevation, detail of window



Plate 13: Building 1 – northwest elevation



Plate 14: Building 1 – northwest elevation, remains of stone masonry and blocked doorway



Plate 15: Building 1 – northwest elevation viewed from inside a later store




Plate 16: Building 1 – northwest elevation with inserted opening



Plate 17: Building 1 – northwest elevation with blocked arched doorway



Plate 18: Building 2 – aerial view of the southwest elevation



Plate 19: Building 2 – aerial view of the northeast elevation with a later open-fronted lean-to extension



Plate 20: Building 2 – southwest elevation and contiguous Building 3 to the right



Plate 21: Building 2 – southwest elevation, detail of staggered construction joints



Plate 22: Building 2 – southwest elevation, detail of successive brickwork construction




Plate 23: Building 2 – southwest elevation, central doorway and later window opening



Plate 24: Building 2 – southwest elevation, doorway to the northwest and incised graffiti '1861' (arrow)



Plate 25: Building 2 – southwest elevation, detail of first-floor window opening



Plate 26: Building 2 – northeast elevation with open-fronted lean-to extension



Plate 27: Building 2 – northeast elevation, leant-to extension and blocked first-floor window openings



Plate 28: Building 3 – aerial view of the southwest elevation abutted by Building 4 to the right



Plate 29: Building 3 – aerial view of the southeast gable elevation



Plate 30: Building 3 – general view to the rear side with later lean-to extension



Plate 31: Building 3 – southwest elevation




Plate 32: Building 3 – southwest elevation, doorway and construction joints



Plate 33: Building 3 – southwest elevation, inserted ground-floor window opening



Plate 34: Building 3 – southwest elevation, southeast end abutted by Building 4



Plate 35: Building 3 – southwest elevation, detail of first-floor window opening



Plate 36: Building 3 – southeast elevation



Plate 37: Building 3 – southeast elevation, detail of doorway flanked by section of stone masonry



Plate 38: Building 3 – northeast elevation with lean-to extension



Plate 39: Building 3 – northeast elevation, southeast end of the lean-to extension



Plate 40: Building 4 – aerial view of the northwest elevation



Plate 41: Building 4 – northwest elevation with contiguous Building 5 to the right



Plate 42: Building 4 – northwest elevation, detail of central doorway



Plate 43: Building 4 – northwest elevation, detail of construction joint to Building 5



Plate 44: Building 4 – southeast elevation



Plate 45: Building 5 – aerial view of the northwest elevation



Plate 46: Building 5 – northwest elevation



Plate 47: Building 5 – northwest elevation, detail of central doorway



Plate 48: Building 5 – northwest elevation, detail of runout stop chamfered wall plate



Plate 49: Building 5 – southeast elevation with contiguous Building 4 to the right



Plate 50: Building 5 – southeast elevation



Plate 51: Building 5 – southeast elevation, blocked doorway to the southwest end



Plate 52: Building 6 – aerial view with cross wing Building 5 to the left



Plate 53: Building 6 – southwest open-fronted elevation



Plate 54: Building 6 – northwest gable elevation



Plate 55: Building 6 – northeast elevation



Plate 56: Building 6 – southeast gable elevation



Plate 57: G1 – southeast wall with doorway and window opening




Plate 58: G1 – construction joint of former opening to the right of the window opening



Plate 59: G1 – northwest wall with remains of stone masonry



Plate 60: G1 – detail of blocked ventilation slit and doorway




Plate 61: G2 – southeast wall with construction joint to the gable wall




Plate 62: G2 – gable with taking-in door and adjacent iron bracket of former hoist



Plate 63: G2 – later doorway blocked with concrete blockwork




Plate 64: G2 – southwest gable wall



Plate 65: G2 – detail of queen-post truss




Plate 66: G2 – northwest wall




Plate 67: G2 – detail of large arched doorway




Plate 68: G2 – southwest gable with roller shutter and window opening above




Plate 69: G3 – passage with doorway to the courtyard



Plate 70: G3 – blocked doorway to G2



Plate 71: G3 – blocked ventilation slit



Plate 72: G3 – northwest doorway and construction joint



Plate 73: G4 – doorway to the courtyard



Plate 74: G4 – concrete boskin and stalls



Plate 75: G4 – concrete boskin with drainage gully



Plate 76: G4 – doorway to G6



Plate 77: G5 – arched doorway to passage G3



Plate 78: G5 – northeast wall with lower stone masonry



Plate 79: G5 – southeast wall



Plate 80: G6 – doorway to G4