



CSD1	442464.930	302553.087	126.159
CSD2	442419.161	302601.532	125.925
CSD3	442467.319	302619.680	124.835

Floor Plan Legend:

Window Sill & Head Height
SH: Sill Height From FFL
HH: Head Height From FFL

Door Height From FFL

Overhead Detail

Stairs/Step

Radiator

Ventilation / Overhead

Access Hatch

TV Point

Phone Point

13A Power Socket

Fused Socket

Shaver Socket

Extractor Fan

Lantern Light

Down Light

Light Dimmer Switch

Light Switch

Fire Alarm Button

Fire Extinguisher

Room Name

Floor Covering

Ceiling Height

Internal Floor Level

Topographic Legend:

Buildings / Walls

Building Canopy / Overhang

Concrete edge

Kerb line

Centre Line

Barrier

Hedge

Panel Fence

Gate

Overhead Line

Tree / Sapling

Tree Canopy Line

Chambers

Survey Station & Name

Bench Mark

Temporary Bench Mark

Cover level

Invert level

Pipe Invert (diameter)

Gully

Manhole

Inspection chamber

N

CASTLE SURVEYS LTD
info@castlesurveys.co.uk
WWW.CASTLESURVEYS.CO.UK

CHAS
Approved Contractor

THE SURVEY
ASSOCIATION

Achilles

CYBER
ESSENTIALS

Constructionline
Gold Member

SITE DETAILS:

Cadeby Hall, Cadeby Nuneaton, CV13 0AX

TITLE:

Topographical

DRAWING NO.:

26390-26-01

SCALE:

1: 200

DATE:

05/06/26

REV:

-

Comments:

This plan should only be used for its original purpose. Castle Surveys Ltd does not accept any responsibility for this plan if supplied to any other party, other than the original client.

All dimensions and levels should be checked on site prior to design and construction.

This survey has been orientated to the Ordnance Survey (O.S.) National Grid (OSGB36) Via a global position system (GPS) and the O.S. Active Network (O.S. NET).

A true OSGB36 coordinate has been established near to the site centre via a transformation using the OSTN15 & OSGB15 transformation models.

The survey has been correlated to this point and further one or more OSGB36 points established to create a true O.S. bearing for angle orientation.

No scale factor has been applied to the survey therefore the coordinates shown are local plane grid.

Please refer to survey station table to enable establishment of the on-site grid.

Drainage information (where applicable) has been visually inspected from the surface and therefore should be treated as approximate only. Some services may have been omitted due to parked vehicles or due to the site being overgrown with vegetation.

Tree information (where applicable) has been surveyed from ground level and therefore should be treated as approximate only. Advise that a tree survey should be carried out. Roof line work (where applicable) is indicative only.

DRAWN:

DB

CHECKED:

CL

LEVEL DATUM:

OSGB36(15)

DO NOT SCALE

Paper Size - A0

©Copyright Castle Surveys Ltd 2026