Appendix B. Site Photographs

(Taken clockwise when entering the site)



Photo. 1

Showing the side elevation of the principal dwelling to the left. The two-storey rear wing of the principal dwelling is in the centre. The single-storey former outbuildings are just visible to the far right.



Photo. 2

Showing the single-storey former outbuildings to the left. The two-storey former barn/outbuilding in the centre. The access from the courtyard to the application site is to the far right, as highlighted.



Photo. 3

Showing the access from the courtyard to the application site in the centre, as highlighted. The single-storey former outbuildings continue to the right.

Appendix B. Site Photographs

(Taken clockwise when entering the site)



Photo. 4

Showing the access from the courtyard to the application site in the centre. The single-storey former outbuildings continue to the right.



Photo. 5

Showing the access from the courtyard to the application site, the restricted width and the very close proximity to the residential units to both sides. Note the proximity of the windows to either side.